



**MITSUBISHI MOTORS AUSTRALIA LIMITED**

ABN 53 007 870 395

**Head Office**

1284 South Road Clovelly Park, S.A. 5042

PO Box 8, Melrose Park South Australia 5039

Ph: +61 1300 13 12 11 Fax: +61 1300 55 33 19

## Mitsubishi Motors Australia Limited (MMAL)

### Recall Initiation Schedule

Version: 2.0

Issued: 3<sup>rd</sup> September 2018

<b>Recall initiation date</b>	9 <sup>th</sup> April 2018
<b>Make and model</b>	Make: Mitsubishi, Model: CS0A/W, CT9A Lancer
<b>Model year</b>	Affected vehicles were manufactured from 11 <sup>th</sup> June 2003 to 30 <sup>th</sup> December 2008
<b>Geographic application</b>	Not applicable
<b>VIN list</b>	VIN List provided when MMAL initiated this recall by submitting a request for a PRA to ACCC.  <a href="https://www.mitsubishi-motors.com.au/uploads/pdf/recalls/20180403_VIN_List.pdf">https://www.mitsubishi-motors.com.au/uploads/pdf/recalls/20180403_VIN_List.pdf</a>
<b>Other factors</b>	<p>This recall is initiated to rectify Mitsubishi Lancer vehicles which have already had their Takata airbag inflators replaced with Takata airbag inflators of the same type under PRA Number 2015/14936, Campaign Number 010093 which was published on 1<sup>st</sup> October 2015.</p> <p>This recall will rectify affected vehicles with a replacement airbag inflator manufactured by Daicel Corporation.</p>